




FORMLABS USAGE GUIDE:

Castable Wax: Jewelry Pattern Burnout Process

A 20% wax-filled material for reliable casting with zero ash content and clean burnout, Castable Wax accurately captures intricate features and offers the smooth surfaces stereolithography 3D printing is known for. Printed parts are strong enough to handle with no post-cure required, suitable for custom try-ons and direct investment casting.

[Request a Sample Part Printed in Castable Wax](#)

Standard Burnout Schedule




The Standard Burnout Schedule is designed to provide the maximum possible investment strength and complete burnout of the finest details using R&R Plasticast or similar investment materials. Use this schedule as a starting point and make adjustments as needed.

DESCRIPTION	PHASE	TIME TO TEMP	SCHEDULE °C	SCHEDULE °F
A Drying Eliminates water and improves investment strength.	Insert Flasks	0 min	150 °C	302 °F
	Hold	60 min	150 °C	302 °F
B Thermal Transition Wax melts out, increasing airflow to the resin pattern. Burnout begins gently, breaking down the pattern without excessive expansion.	Ramp	100 min	2.2 °C/min	4.0 °F/min
	Hold	120 min	371 °C	700 °F
C Burnout Eliminates the remaining resin in the investment.	Ramp	180 min	2.0 °C/min	3.6 °F/min
	Hold	280 min	732 °C	1350 °F
D Casting Temperature Cools the flask to casting temperature of the selected metal.	Ramp	100 min	-2.2 °C/min	-4.0 °F/min
	Casting Window	Up to 2 hours	512 °C (or casting temperature of alloy)	954 °F (or casting temperature of alloy)

Before Casting: It is important to thoroughly clean prints before use. Wash Castable Wax prints in isopropyl alcohol (IPA) for 10 minutes. Rinse for 5 minutes in a second, cleaner IPA bath to eliminate any remaining uncured material. For best results, fully dry parts with compressed air. No post-curing is required for Castable Wax parts.

Short Burnout Schedule



It is possible to achieve faster cycle times with some geometries and investment materials. Higher end investments, such as R&R's Ultravest Maxx, are stronger and can withstand faster heating.

Consider a fast burnout schedule if parts are thin (weigh less than 1 g per piece) and total flask volume is low (flask less than 6" tall).

The cured flask is placed directly into a preheated furnace, and can be cast after 8 hours. Time at peak temperature may be reduced or extended depending on the volume of the parts.

	DESCRIPTION	PHASE	TIME TO TEMP	SCHEDULE °C	SCHEDULE °F
A	Thermal Transition	Insert Flasks into hot oven	0 min	371 °C	700 °F
		Hold	60 min	371 °C	700 °F
B	Burnout	Ramp	120 min	3.5 °C/min	6.3 °F/min
		Hold	240 min	788 °C	1450 °F
C	Casting Temperature	Ramp	60 min	-4.6 °C/min	-8.3 °F/min
		Casting Window	Up to 2 hours	512 °C (or casting temperature of alloy)	954 °F (or casting temperature of alloy)

Tip: Allow your investment to bench set at room temperature for 2-6 hours after mixing. Bench set time allows the investment to cure and strengthen, important when inserting the flask directly into a hot oven.

Technical Data for Castable Wax FLCWPU - Green¹

	METRIC ²	IMPERIAL ²	METHOD
Tensile Properties			
Ultimate Tensile Strength	22.5 MPa	3270 psi	ASTM D 638-10
Young's Modulus	0.94 GPa	13 ksi	ASTM D 638-10
Elongation at Break	13%	13%	ASTM D 638-10
Burnout Properties			
Temp @ 5% Mass Loss	249 °C	480 °F	ASTM E 1131
Ash content (TGA)	0.0 - 0.1%	0.0 - 0.1%	ASTM E 1131

NOTES:

¹Data was obtained from green parts, printed using Form 2, 50µm, Castable Wax settings without additional treatments.

²Material properties can vary with part geometry, print orientation, print settings, and temperature.